

### **Update-Information for DSPTNC/Tracker-Firmware: Version 1.3**

Firmware version 1.3 is a general bugfix update. Some internal structures were rewritten in order to increase efficiency and stability of the firmware. We recommend to upgrade to firmware version 1.3, although it does not provide new features. Especially the problem of sporadic parameter inconsistencies between TRConfig and the DSPTNC/Tracker will be fixed by version 1.3.

By the way, the DSPTNC/Tracker now immediately transmits the first position report (APRS) in “tracking mode” right after reading the first valid GPS information, i.e. after power-up the tracker does no longer delay the first position report until the first “sleep interval” is over.